

























SYMBOLS

FUNCTION

EXAMPLE

SYMBOLS	FUNCTION	EXAMPLE
	Elbow	
	Swivel elbow	
	Adjustable locknut elbow (O. ring)	
	Adjustable locknut elbow (O. ring and retaining ring sealing)	
	Bulkhead elbow	
	Tee	
	Swivel branch tee	
	Swivel run tee	
	Adjustable locknut branch tee (O. ring)	
	Adjustable locknut branch tee (O. ring and retaining ring sealing)	
	Adjustable locknut run tee (O. ring)	
	Adjustable locknut run tee (O. ring and retaining ring sealing)	


SYMBOLS

FUNCTION

EXAMPLE



Union
(O. ring)



Union
(E form)



Union tube to tube



Bulkhead union



Swivel connector
(O. ring)



Swivel connector
(E form)



Swivel union




Swivel union



Female connector



Swivel female connector



Cross union

